Fiber OWL 4 Series Test Kits

Certification Testing

Quick Reference Guide

For part numbers: KIT-FO4-WSSDst KIT-FO4-WSSDsc KIT-FO4-WSSDfc



Optical Wavelength Laboratories

Revision 1.0

Date: July 1, 2008

Whitewater, WI 53190 Phone: 262-473-0643 Internet: OWL-INC.COM

NOTICE TO NEW USERS:

All personnel testing optical fibers should be adequately trained in the field of fiber optics before using any fiber optic test equipment.

If the user is not completely familiar with testing fiber optics, they should seek competent training. Such training can be acquired from a variety of sources, such as local hands-on training classes.

Valuable information about fiber optic testing can also be gathered from reading printed literature carefully or by thoroughly reading supplied operations manuals.

Fiber optic testers vary from other types of test equipment due to issues such as:

- 1) standards-based testing
- 2) proper fiber optic test procedures (FOTPs)
- 3) "zeroing" or referencing of power levels
- 4) determining the correct link budget to pass or fail by

Complete understanding of each of these issues is critical for performing proper fiber optic tests.

GETTING STARTED

Thank you for your purchase of this OWL certification test kit. Included in this kit is a Fiber OWL 4 optical power meter and a WaveSource singlemode fiber optic laser source. This quick reference guide will assist you in setting up your test kit for a standards-based certification test.

BEFORE YOU TEST

Prior to performing a certification test, there are a few things you need to know about your link:

- ➤ Fiber Type
- ➤ Fiber Length
- Number of Connections (i.e. patch panels)
- ► Number of Splices
- ➤ Fiber Cabling Standard
- ➤ Connector Type

It is also important to understand the definition of a fiber optic link as it pertains to the Fiber OWL 4:

A link is a group of fibers that have the same characteristics, and follow the same pathway from one end to the other.


Also, ensure that your patch cable connectors match the patch panel ports on the link under test.

REQUIRED ACCESSORIES

➤ (2) singlemode patch cables

EQUIPMENT PORTS

Figure 1 shows the ports of the equipment used during this procedure. These ports may vary depending upon the model of equipment.



VERIFY PROPER OPERATION OF THE EQUIPMENT

STEP 1 Connect the power meter and light source together with one of the patch cables as shown in Figure 2.



- **STEP 2** Power on the light source, and press the < **PORT>** button to switch to the SM PORT. The indicator LED on the right-hand side should be red (1310nm).
- **STEP 3** Power on the Fiber OWL 4.
- **STEP 4** From the OPERATING MODE menu, select SIMPLE METER.
- **STEP 5** Press < F3 > until the Fiber OWL 4 is set to 1310nm wavelength.
- **STEP 6** The power reading on the Fiber OWL 4 should be approximately -10.00 dBm. If the reading is -12.00 dBm or below, it is recommended to replace the cable.
- **STEP 7** Once proper operation has been verified, remove the first patch cable from both units and set it aside.
- **STEP 8** Connect the second patch cable between the Fiber OWL 4 and the WaveSource, as shown in Figure 2.
- STEP 9 The power reading on the Fiber OWL 4 should be approximately -10.00 dBm. If the reading is -12.00 dBm or below, it is recommended to replace the cable.

VERIFY PROPER OPERATION OF THE EQUIPMENT, cont.

STEP 10 Once proper operation has been verified, press **< DONE>** to return to the OPERATING MODE menu.

RUN LINK WIZARD

STEP 11 From the OPERATING MODE menu, select CERTIFICATION METER.


STEP 12 From the START MENU, press <1>LINK WIZARD.

START MENU <1>LINK WIZARD <2>TAKE READINGS <3>MAIN MENU

STEP 13 From the STORED LINKS menu, highlight the stored link name you wish to use and press <**F2**> to select.




STEP 14 OPTIONAL: you may change the link name to something that better describes the group of fibers you are testing.



Press < DONE > to continue.

STEP 15 Change the LINK DATE to the date the fiber will be tested using the format MM-DD-YY.



Press **<DONE>** when you are finished entering the current date.



It is important to set the current date in order to ensure that the correct date appears on the certification report.

STEP 16 Highlight the cabling standard to use for the set of fibers you are testing.

Press $\langle F2 \rangle$ to select the chosen standard.



STEP 17 Highlight the fiber type of the network under test.

Press <**F2**> to select the fiber type.



STEP 18 Enter the length of the fiber link under test from end-to-end in meters.

Press **< DONE>** to continue.




STEP 19 Enter the number of connections (i.e. patch panels) in the link under test. Typical fiber networks will have 2 connections – one for a patch panel located at each end of the link.

Press < DONE > to continue.



STEP 20 Enter the number of splices in the link under test. Splices can be either fusion or mechanical. Typical singlemode networks will have zero splices.



NOTE: some connectors use mechanical splice technology for termination. If the link under test is terminated with these "no-polish, no-epoxy" type connectors, they should be considered as mechanical splices.

Press < DONE > to continue.

RUN LINK WIZARD, cont.

STEP 21 Review your Link Wizard setup.


If correct, press $\langle F1 \rangle$ and continue on to the next step.

If changes need to be made, press <F3> and go back to STEP 14.

STEP 22 Press < F1 > until the asterisk (*) is in front of 1310nm (as shown at right).

Press < F2 > to begin the SET REFERENCE procedure for 1310nm.





STEP 23 Connect the detector port on the meter and 1310nm light source (right-hand port) together with a singlemode cable as shown in Figure 2 (on the reverse side of this page).

Press < F1 > to continue.

1310nm SOURCE

STEP 24 Make sure that the 1310nm light source port is powered ON and selected (the indicator LED on the right-hand side will be the color red).

STEP 25 Confirm setting the 1310nm reference.

Pressing <F1 > to continue. You will be returned to the SET SOURCE REFERENCES screen.



STEP 26 For setting a 1550nm reference, repeat steps 23 through 26, except you will press < F1 > to select 1550nm (as shown at right). Also make sure that the WaveSource is set to 1550nm (the right-hand indicator LED will be the color green).



After the 1550nm reference is set, the **REF dBm** field will be filled in with a reference value.

STEP 27 Press < F3 > to complete the Link Wizard.

STEP 28 Press <F1 > to begin taking readings.

TAKE READINGS

STEP 29 If testing two wavelengths, press the <AUTO> button to set the Fiber OWL 4 into AUTO mode, then press and hold the λ /AUTO button on the WaveSource. You will begin to see the WaveSource indicator LED alternate between green and red.

STEP 30 Disconnect the singlemode patch cable from the Fiber OWL 4 and take the units to opposite ends of the link.




Do NOT disconnect the patch cable(s) from the light source at any time until all fibers have been tested.

(continued on next page)

TAKE READINGS, cont.

STEP 31 Connect the units to the first fiber to test as shown in Figure 4. Your readings will vary from the example below.



- **STEP 32** Once the STORE button becomes active, press <**F2**> to store the data point. If this is the first fiber in the link, you may be prompted to enter a new label.
- **STEP 33** Press < **F3** > to save the data point.
- **STEP 34** Disconnect the patch cables from the patch panels and move them to the next port in the patch panel, then repeat steps 32 through 34 until all fibers in the link have been tested.